

RS31 OS Image Release – V5059

[Applied Model]

RS31 OS Image

[New Features]

1. Enterprise Settings & Enterprise Service update to V1.0.15.
 - Add to save the settings as a json file for ADC setup.
2. CustomizeSetupWizard update to V1.0.2.
 - Support enroll device by ReMoCloud.CustomizeSetupWizard update to V1.0.5
 - Support SOTI enrollment.
4. [Framework][Reader Service] Support Fast KeyEvent and IME Delay.
5. Reader Config update to V1.3.9.
 - Support to add 50 rules/actions.
 - Add "Timeout Between Input Method".
 - Add "Advanced Data Formatting" password-protected.
 - Keyboard Emulation add "Copy & Paste".Reader Config update to V1.3.12
 - Support SE4850 more Scan Mode.
 - Support SE4500/4750/4770/SDC to Chinese 2 of 5 Code Lengths (8 - 55).
6. A-Demo update to V1.0.5
 - Add Text Recognition Demo (this function is supported by Google Play Service v20 or later).
 - Add Inventory Management Demo.
8. Add Device Health Dashboard V1.0.0
 - Separate the UI of Device Health into this app.

[Modification]

1. AppLock update to V1.2.11.
 - Target SDK version change to 28.
2. CustomizeSetupWizard update to V1.0.3.
 - Remove Quit button.

3. Reader Service update to V1.3.31.
 - Rollback SDL library to SDL-ALASPR36547-008-N05.
 - Replace Zebra Video Mode to Aim Mode.
4. Remove webkey.
5. Device Health Dashboard update to V1.0.1.
 - Information of Sub Battery doesn't display.

[Bug Fixed]

1. ADCClient update to V1.2.61.
 - Fix the issue that can't use Zip file in SD Card/from URL.
2. BarcodeToSetting update to V1.07.5.
 - Fix the issue that it won't open app after restart the device if select "File from auto installation" in "Auto Run" tab of ADC.
 - Fix the issue that showing error message "The data length of barcode is different from header file" when setting "Data Output" in Reader Config.
3. AppLock update to V1.2.11.
 - Fix the issue of RK95 keypad.
4. Reader Service update to V1.3.31.
 - Fix the issue that the last barcode is ":" but not showing up in output.
- Reader Service update to V1.3.34
 - Fixed license failure when update OS.
5. SIPController update to V1.0.16.
 - Fix the issue of ADC setting icon status.
 - Fix the issue of the error crash for setting.json format.
6. SoftwareTrigger update to V1.1.8.
 - Fix the issue that icon does not match the setting value after ADC Deploy UI synchronization and reboot.
7. CustomizeSetupWizard update to V1.0.4
 - Fix the issue that ADCClient appear "Fail" after deploying Wi-Fi setting to OS.
 - Fix the issue of Reader initialization. It must be initialized after receiving BOOT_COMPLETED to avoid the problem that the reader may be unavailable.