

RS30 OS Image – V5720

[Applied Model]

RS30 OS Image

[New Features]

1. BarcodeToSetting update to V1.0.3.8.
 - Unknown Source option can be opened directly through WMDS/ADC.
2. ADCClient update to V1.2.27.
 - Unknown Source option can be opened directly through WMDS/ADC.
3. AppLock update to V1.2.2.
 - Add Log function (options are located in Menu -> Options... -> Security -> Enable Log, default value: Disable).
 - Add custom Package naming rule. After adding a rule, it will automatically add the related apps to the Allowed list (Apps that meet the rules are also allowed to be installed and automatically added to the desktop).

[Modification]

1. AppLock update to V1.2.2.
 - The button of the "Add New App" on the Applications Management page is changed to a floating button.

[Bug Fixed]

1. Fix the issue of screen flicker.